



Suitable For Underfloor Heating Suitable for Wet Areas Slip Resistant Castor Chair Compatible (only when glued down) SuperGuard Stain Shield Indoor Air Quality Anti Skid

Construction	Acoustic Luxury Vinyl Tile	
Plank Size	178mm x 1220mm	
Tiles per Carton	10pcs / 2.17m ²	
Total Weight	8400g/m ²	
Wearlayer Thickness	0.70mm	
Total Thickness	5.0mm	
Bevel	V-groove, 4-sided bevel	
Surface Protection	Superguard®	
Slip Resistance	Pattern	Slip Resistance (oil-wet ramp, AS NZS 4586:2013)
	European Oak 2870	R9
	European Oak 2951	R9
	Riviera Oak 1240	R10
	Swedish Pine 2242	R9
	Swedish Pine 2965	R9
	Traditional Oak 1826	R10
	Traditional Oak 1832	R10
Electrical Propensity	<2kV (EN 1815)	
Electrical Resistance	≤10 ⁹ Ohm (ISO 1081)	
Fire Rating	CRF 8.7kW/m ² (ISO 9239-1)	
Acoustic Insulation	ΔLw = 8 dB (EN ISO 10140-3)	
Dimensional Stability	≤0.10% (ISO 23999)	
Thermal Insulation	0.25w/(m.K) (EN 12524)	
Thermal Resistance	0.0223m ² .K/W (EN 12664)	
Underfloor Heating	Suitable, max 27°C (EN 12524)	
Wet Areas	Suitable (ISO 4760:2022)	
Residual Indentation	≤0.10mm (ISO 24343-1)	
Colour Fastness	≥6 (ISO 105-B02)	
Formaldehyde Group	E1 (EN 717-1)	
Classifications	Class 23 Domestic Heavy / Class 34 Commercial Very Heavy / Class 43 Industrial Heavy	
Warranties	LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty	
Environmental	Indoor Air Quality - adheres to German AgBB Standards.	
Installation	Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.	

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- **Rubber Migration:** Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.