Ultimo II

(only when glued down)

Belgotex[•]



Construction Luxury Vinyl Tile Plank Size Classic: 196mm x 1320mm London Plank: 94mm x 282mm Classic: 14pcs / 3.62m² **Tiles per Carton** London Plank: 92pcs/2.44m² Total Weight 4059g/m² Wearlayer Thickness 0.55mm Total Thickness 2 5mm Bevel V-groove, 4-sided bevel Surface Protection Superguard® R9 (AS NZS 4586:2013) Slip Resistance **Electrical Propensity** <2kV (EN 1815) ≤10⁹ Ohm (ISO 1081) **Electrical Resistance** CRF 9.0kW/m² (ISO 9239-1) Fire Rating 4dB (EN 140-8) Acoustic Insulation **Dimensional Stability** ≤0.05% (ISO 23999) Thermal Insulation ≤0.25W/m/K (EN 12524) Thermal Resistance 0.01m² K/W (ISO 12664) Underfloor Heating Suitable, max 27°C (EN 12524) Wet Areas Suitable (ISO 4760:2022) **Residual Indentation** ≥0.10mm (ISO 24343) **Colour Fastness** ≥6 (ISO 105-BO2) Formaldehyde Group E1 (EN 717-1) Classifications Class 23 Domestic Heavy / Class 33 Commercial Heavy / Class 42 Industrial Medium Warranties LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty Environmental Greentag Certified, BREEAM certified (ENP 461) FloorScore[®], A+ Emissions Installation Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.

For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz

Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.

This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.

Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.

Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.

